

BUILDING SAFETY CERTIFICATE

Letter No. 1382/162/.....

Dated 26/06/25.


It is certified that the existing building **Gurukul Academy** at **Daurala, District-Meerut (U.P.) 250221** is having block(s) /Floor(s) as per details below:

Detail of Block(s) in School	(Block) (1)	(Block) (2)	(Block) (3)	(Block) (4)	(Block) (5)
No. of Floor(s) in the Block	Ground Floor + 1 st Floor	-	-	-	-

The building is owned/occupied by **Jagriti Foundation Trust, Urmila Green Colony, Daurala Sub-Division-Sardhana District- Meerut (U.P.) Gurukul Academy** have complied with the Building safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of **Construction Division, Public Work Department, Meerut (U.P.)** On 24-05-2024 in the presence of **Mr. Govind Ahlawat (Manager of Gurukul Academy) Town and Post- Daurala, District-Meerut (U.P.) 250221** and that the building/premises is fit for occupancy for running school with effect from **27-07-2024** for a period of **03 years** in accordance with the rule and subject to compliance of the specific conditions as appended.

1. Prima facie the construction of building seems to be as per norms of National Building Code rules but in case the building is not found in conformity of detailed National Building Code rules the Public Work Department shall not be held accountable.
2. This certificate is not valid for legal purpose if any litigation persist currently or in future during the above said period for which certificate issuing authority is not accountable.

Issued on ..26/6/25..... at PWD Office, Meerut by Executive Engineer,, Construction Division, Public Work Department, Meerut.



(Sanjay Singh)
Executive Engineer
CD.PWD,MEERUT
मेरठ